

Report No.:SZA EK190830006-01

Test Report

Client Name : BLUEVISION (SHENZHEN) OPTOELECTRONICS CO., LTD

Address : 2nd Floor, Building 6, Nangang 3rd Industrial Park, Tangtou, Shiy an Town, Bao'an District, Shenzhen, China

Product Name : Waterproof Linear Light Fixture

Date : 2019.09.06



Shenzhen Anbotek Compliance Laboratory Limited

Shenzhen Anbotek Compliance Laboratory Limited

Address: East of 4/F., Building A, Hourui No.3 Industrial Zone, Xixiang Street, Bao'an District, Shenzhen, Guangdong, China

Tel:(86)755-26066126 Fax:(86)755-26066021 Email:service@anbotek.com

Code:AB-AR-02-c

Page 1 of 7



Hotline

400-003-0500

www.anbotek.com

Report No.:SZAEK190830006-01

Marking

1. The test report is invalid without the official stamp of Shenzhen Anbotek Compliance Laboratory Limited.
2. Nobody is allowed to photocopy or partly photocopy this test report without written permission of Shenzhen Anbotek Compliance Laboratory Limited.
3. The test report is invalid without the signatures of testing engineer, reviewer and approver.
4. The test report is invalid if altered.
5. Objections to the test report must be submitted to Shenzhen Anbotek Compliance Laboratory Limited within 15 days.
6. The test report is valid for the tested samples only.
7. As for test verdict, “—” means “no need for judgment” “N/A” means “not applicable”.

Shenzhen Anbotek Compliance Laboratory Limited

Address: East of 4/F., Building A, Hourui No.3 Industrial Zone, Xixiang Street, Bao'an District, Shenzhen, Guangdong, China

Tel:(86)755-26066126 Fax:(86)755-26066021 Email:service@anbotek.com



Hotline

400-003-0500

www.anbotek.com

Report No.:SZAEEK190830006-01

TEST REPORT

Client Name : BLUEVISION (SHENZHEN) OPTOELECTRONICS CO., LTD
Address : 2nd Floor, Building 6, Nangang 3rd Industrial Park, Tangtou, Shiyan Town, Bao'an District, Shenzhen, China


Report on the submitted sample(s) said to be:

Product Name : Waterproof Linear Light Fixture
Model : Please see the next page.
Trademark : BLUEVISION
Description : /
Sample(s) received quantity : 1pc
Sample(s) Testing quantity : 1pc
Manufacturer : BLUEVISION (SHENZHEN) OPTOELECTRONICS CO., LTD
Factory : BLUEVISION (SHENZHEN) OPTOELECTRONICS CO., LTD
Other information : /
Sample(s) received Date : 2019.08.30
Testing period : 2019.09.03
Report Date : 2019.09.06

Test Conclusion :

Item No.	Test Item	Test Standard	Evaluation
1	IK10	IEC 62262:2013	Pass

Prepared by:




Name: Carlos Ye
 Title: Test Engineer

Checked by:



Name: Jimmy Zhou
 Title: Lab Manager

Approved by:



Name: Mike Jiang
 Title: Authorized signatory

**Shenzhen Anbotek Compliance Laboratory Limited**

Address: East of 4/F., Building A, Hourui No.3 Industrial Zone, Xixiang Street, Bao'an District, Shenzhen, Guangdong, China
 Tel:(86)755-26066126 Fax:(86)755-26066021 Email:service@anbotek.com



Hotline
 400-003-0500
 www.anbotek.com

Report No.:SZA EK190830006-01

Ordinal No.	Product Name	Model	Note
1	Waterproof Linear Light Fixture	L8989-NW45S	Test sample
2		L8989-a45X	/
3		L8989-a68X	/
4		L8989-a90X	/

Remark :

1.A is the color temperature code; WW = 2700K, 3000K or 3500K ; NW = 4000K or 4500K ; W = 5000K, 5500K, 6000K or 6500K ; X represents type: for example, S is the power cord ;



2.Series models have the same structure as the main inspection model, but different power and length.




Report No.:SZA EK190830006-01

1. IK10				
Test Standard	IEC 62262:2013			
Test Condition	<p>The test remark and the matters needing attention:</p> <p>--- the sample is Installed on the rigid support surface, Begin the impact test from a height of 400 mm using the pendulum 5 kg, The energy of impact test specimens for 20J;</p> <p>--- The impact of 5 points evenly distributed in the each exposed surface of the sample;</p> <p>--- There shall be no more than three collisions applied near the same position of the enclosure;</p> <p>--- Check the sample after the test.</p>			
Test Equipment	Equipment Name	Equipment No.	Equipment model	Equipment Cal validity period
	IK impact tester	SE-1459	GRPH-2	2019.12.19
Test Result	Sample No.	Test requirements	Test Result	Evaluation
	SZA EK190830006-S1	The sample housing is allowed to be slightly cracked, dented and not to be seriously damaged.	The sample housing has no slight crack, no serious damage ,and slight depression.	Pass
Photos				
	Before test		Before test	

Report No.:SZAEK190830006-01

		
	<p>Before test</p>	<p>Before test</p>
<p>Photos</p>		
	<p>Test set-up</p>	<p>Test set-up</p>
		
	<p>Test set-up</p>	<p>Test set-up</p>

Report No.:SZA EK190830006-01

Photos		
	After test	After test
		
	After test	After test

End of Report

